

IP-BSM Status and Plan



11th ATF2 Project Meeting

Jan. 13, 2011

SLAC National Accelerator Laboratory
Menlo Park, California

Jacqueline Yan, M. Oroku, Y. Yamaguchi,
T. Yamanaka, Y. Kamiya, T. Suehara,
S. Komamiya (The University of Tokyo)
T. Okugi, T. Terunuma, T. Tauchi, S. Araki, J. Urakawa (KEK)



layout

- Beam time results of Nov /Dec of 2010
 - 2-8 degree mode
 - 30 degree mode
 - reasons we could not detect modulation
- **Laser system status**
 - **Laser focusing problem**
 - What happened?
 - possible causes
 - **Laser timing problems**
 - Timing system renewal
 - **detector gate timing**
- **Plan from 2011 Jan~**

Laser Problems (last beam time)

Thur (12/16) → Fri. (12/17):

Attempting **30 deg mode** directly from 6 deg

(1) laser timing messed up

- Beam and laser interference fringe ceased to collide
- *Lost modulation*

(2) Unfocused laser spot size at IP

low S/N




Switched back to 7.79 deg

- tried to control laser timing
- **Re-conducted laser wire scan, z – scan**

➔ collision temporarily resumed

BUT modulation get lost on and off

- beam intensity and laser timing remained unstable




Unfocused Laser

lower laser path unfocused :

$$\sigma_{\text{laser } 2}(30^\circ) = 28.03 \mu\text{m}$$


➤ Wide laser wire scan peaks

c.f. design size $\sim 10 \mu\text{m}$



Upper path :

$$\sigma_{\text{laser } 1}(30^\circ) = 11.13 \mu\text{m}$$



Where to blame for unfocused laser??

(1) cooling water suddenly fell below safety line → interlock gave off

➤ Air bubbles got in during replenishing

May have.....

- blocked excitation lamp, disturbed seeder
- re-circulated (> 50 times)


(2) abrupt interlock stop → took time to recover

➤ affected upper path also (recovered later)

(3) Changed lower path lens at 30 deg
(possibly in wrong direction)

➤ However is 8 deg focused??

$$\sigma_{\text{laser2}} = (7.79^\circ) = 27.9 \mu\text{m}$$



More on Cooling Water


Startup day: tank 1/5 full

- couldn't find leak
- ❑ Evaporate rapidly if used over 10 hrs everyday, esp. during dry climate
- *must be cautious from now on*
- **New tank** (see next slide)

Checked: cooling water purity is not the problem

in fact, purer than ATF purified water sample

resistivity: [$\Omega \cdot \text{cm}$] IP-BSM: 1.57×10^6 ATF sample: 7.72×10^5



External cooling water tank

(1) Fast evaporation due to unclosed system

- extend two hoses to outside of power source
- Connect to **new tank**
- Tank **lid sealed tight** with rubber
- **insulate hose and tank** (laser sensitive to temperature)

(2) water level judged only visually

no alarm: abrupt interlock stop


- Switch interlock connections from current tank to new tank
- New tank has monitors: constant display + alarm
- **Water level monitor** : connection to current water level interlock
- **Flow monitor** : interlock connection to laser power source

(3) Air bubbles get in during refill or exchange


- Hand-powered **valves** on hose connector: **seal tight during refill**

laser –beam timing: 97 ns difference required

Beam: stripline timing BPM (upstream)





Laser: PIN-Photodiode




TDC START:

laser output synchronized
with Q-switch



laser Q-switch timing



- Triggered Flash Lamp creates light pulse
- **Max Laser power extraction if Q-Sw triggered $\sim 180 \mu\text{s}$ after FL trigger**
- Output $\sim 100 \text{ ns}$ after Q-switch trigger
- **laser pulse width = 8 ns (FWHM) after SHG ($1064 \rightarrow 532 \text{ nm}$)**

Old timing system


laser-beam
collision

FL: Pulse generator
+ gate generator 6.25Hz

separate ref.
signals
for FL and Q-Sw

Analog delay
modules
180μs

Q-Sw:
Gate generator 1.56 Hz



Laser Timing Problems

FANIN/FANOUT of gate generators taken for Laser Q-switch

① **6.25 Hz** (laser ~ 10 Hz) ② **1.56 Hz** (beam at 1.56Hz)



◆ laser pulse timing disturbed by few hundred ns jitter

➔ prevented beam – fringe collision

few ns scale control required


- Delay on analog modules

Incompatible for fine 100ns step adjustments

(1) 6.25 Hz gate generator ($\sim 100 \mu\text{s}$)

(2) pulse generator ($\sim 800 \mu\text{s}$)

❖ since FL and Q-Sw had separate ref. signals



Timing System Renewal


precise !! simpler!!

- Substitute analog module with **digital TD4**

“double TD4 set”

2.1 MHz (462 ns step) TD4 : rough timing
paired with
357 MHz (2.8 ns step) TD4 : precise work

- simultaneous control of FL and Q-Sw
 - Common upstream ref. signal



- 180 μs delay between FL and Q-Sw
- Precise laser-beam timing

Timing System Renewal

(1). Delay ($\sim 100 \mu\text{s}$) 1.56Hz ref. signal with TD4

(2) Pulse generator ; {1.56 Hz \rightarrow 6.25 Hz} *No more pulse generator delay*


(3) **FANIN/FANOUT**: one branch becomes **Flash Lamp trigger**

(4) Another branch **delayed 180 μs**



\rightarrow become **Q-Switch trigger**

*essential for collision between
beam and laser interference fringes*

- FL and Q-sw triggers proceed into DAQ
- FANIN/FANOUT \rightarrow use in photodiode, peakhold trigger, image sensor of phase monitor



Gamma detector timing



- **16 chan. ADC gate:**
ref. signal from kicker
(~ 1 ms later than laser ref. signal)
delayed ~ 100 μs

Is analog module here ok?

- **Gamma detector PMT output**

Plan for Next Steps (2011 Jan ~)

IP-BSM shift:

- **Test out new laser timing system**
 - No more jittering /drift disturbing beam-laser collision (?)
- **Detector gate timing evaluation**
- **Focus each laser path at IP at 30, 174 deg**
 - determine real causes for previous failures
 - Improve laser cooling system
 - Lens adjustment

Continuous run:

- **Shift to 30 deg mode from 8 deg mode**
(more details coming up tomorrow: “IP-BSM operation”)




Back up

Unfocused laser

1. move to 30 deg
 2. cannot focus bottom path, even when change reducer
increased average to confirm cannot focus (not reliable until here)
 3. changed lens of lower path
Lens may not be the problem because not focused at 8 deg mode either
 4. lower path even fatter
 5. not enough water, interlock gave off during upper path scan
 6. changed lens again in opposite direction
 7. now upper path cannot focus either (from here on very strange)
 8. many times re-circulation
 9. upper path became focused
 10. lower path still cannot.....
- 50 ns detector jitter ????

- Entire New laser timing system





Old timing system during improvement

this was adjusted to ensure laser-beam collision


separate reference signals for flash lamp and Q-Switch

180 μ s delay for laser output at max power

Gate generators



- Entire old laser timing system



laser Q-Switch timing

- Q-switch for **high power, high peak, short pulsed output**
- **Spontaneous change of Q value**
- Nd:YAG laser has long excitation period: large energy stored
- Laser pulse should approach beam bunch (~ 30 ps) for max. Compton signal

1. Flash Lamp: pumping

- Excite levels in crystal (oscillator)

2. Quenching, de-excitation: emitted light oscillate \rightarrow form inverse population

- **Keep Q value low up to here**
- Maintain high loss within oscillator, suppress resonance \rightarrow larger inverse distribution

3. induced (stimulated) emission $>$ absorption

- **boost Q value at moment of max inversion distribution, sudden resonance**