

# IP-BSM Status and Plan


## 12th ATF2 Project Meeting (LCWS 2011)

Sept. 28, 2011  
Granada

**Jacqueline Yan**, M. Oroku, Y. Yamaguchi,  
T. Yamanaka, Y. Kamiya, T. Suehara,  
S. Komamiya (The University of Tokyo)  
T. Okugi, T. Terunuma, T. Tauchi, S. Araki, J. Urakawa (KEK)





# Layout




# Measurement Scheme

**Split into upper/lower path**  
**Optical delay control**  
**phase scan**



**downstream**

Only currently existing device capable of measuring  $\sigma_y < 100$  nm !!



# Expected performance and resolution

$$\sigma_y = \frac{d}{2\pi} \sqrt{2 \ln \left( \frac{|\cos(\theta)|}{M} \right)}$$

$$d = \frac{\pi}{k_y} = \frac{\lambda}{2 \sin(\theta/2)}$$

Crossing angle $\theta$	174°	30°	8°	2°
Fringe pitch $d$	266 nm	1.028 $\mu\text{m}$	3.81 $\mu\text{m}$	15.2 $\mu\text{m}$
Lower limit	25 nm	100 nm	360 nm	1.4 $\mu\text{m}$
Upper limit	100 nm	360 nm	1.4 $\mu\text{m}$	6 $\mu\text{m}$

Assuming ~ 4 % res.


$$37 \pm 1.4 \text{ (stat)} \begin{matrix} +0 \\ -2 \end{matrix} \text{ (sys) [nm]}$$

Resolution < 10% expected for  $\sigma_y$  25 nm ~ 6  $\mu\text{m}$

However.....

- degraded for low S/N
- ~ 15% in Dec, 2010




## Resolution for each mode




# Post Earthquake Recovery and Confirmation

## Confirmation of system

- Inspected each component according to a checklist (see next slide)
- Point is to restore system back to where we left off in the last beam run
- Check for damage (every component!!) , confirm proper function
- reconstruct laser path for each mode
- Confirm with laser wire mode (reducer scan):  
change in size on screen at low power
- Confirm phase scan with phase monitor output
- Additionally focal point scan for 174 deg mode,  
check mover visually



# Checklist



## For example....

- 1 Laser osc. , timing, intensity temperature, PSD
2. DAQ modules, ADC, VME, EPICS, controller stages, read out state
3. Interlock, attenuator, profile
4. Optical components, reducer, PSDs, optical paths
5. Screen monitor, IP mover, viewport safety
6. detector, collimator scan, BG monitor

# Current confirmation status



region	confirmed	still to be resolved
1 laser table	Oscillator, flash lamp Timing, power Temp dependence	
2. DAQ, control system	DAQ modules (ADC, VME,...) Controller stages Thorlab actuators EPICS, data logger	status read out from ATF-menu
3. Transport	Laser profile interlock attenuator	<b><i>Will finish these up soon before beam run begins</i></b>
4. vertical table	Optical components Laser path (2 deg) PSD , PD signals	PSD calibration Laser path for all modes
5. IP	IP mover, screen monitor	PSD calibration Viewport safety test
Post-IP	Detector <b><i>comprehensively!!</i></b> BG monitor	Collimator scan

# Checked every gamma detector component !!

comprehensive check of damage , signal readout, ect...



→ Reassembled, careful of firm connections

LED,  
exchanged  
ref. fibers




HV , cable  
connections,

CsI(Tl) x 7 layers:  
no eliquescency  
2007                      2011



now all confident and  
in mid of cosmic ray test  
(detector recaliberation)

PMTs (x 13):  
windows ok  
Proper gain





# Hardware Upgrades

For .....

- smooth commissioning of higher deg modes
- improving beam size resolution

# Beam size status

Run of May, 2010

“10 x  $\beta_y^*$  optics” low BG, high S/N

$$\sigma_{y,\min}^* = 310 \pm 30(\text{stat.})_{-70}^{10}(\text{syst.}) \text{ nm} \quad @8\text{deg}$$

Run of autumn, 2010 – early 2011

back to nominal optics  $\beta_y^* = 0.1 \text{ mm}$


High BG:  
~ 40 – 130 GeV

Low S/N : ~ 0.5

Minimum beam size:

$$\sigma_y^* = 280 \pm 90 \text{ nm}$$
$$M_{\text{meas}} = 0.918 \sim 0.984$$

(5.96 deg, 14:31 Dec 16, 2010)



# Laser Problems from last beam run

- Could not move on to 30 deg mode (12/16 - 17)  
*attempted 30 deg directly from 6 deg, should have gone from 8 deg*
- unstable beam intensity


## Laser problems :

Unfocused  $\sigma_{\text{laser}}$  at IP  $> 25 \mu\text{m}$  @  $30^\circ \rightarrow$  *low signal, low S/N*


- Laser timing jitters hindered beam-laser collision *resolved !!*  
 $\rightarrow$  Switched to all digital delay control module

Signal jitters !!


ex) could not reconstruct modulation when switching to 30 deg mode in Dec due to **large signal jitters > 30%!!!**




Dec:  
 $M = 0.35$   
 $S/N = 0.6$   
 res. degraded to  $\sim 15\%$



c.f. No jitters



# Major problem !!





M is lost when:  
**signal jitter > ~ M**

Abrupt modulation drop during mode switching

## <<Main causes for signal jitters>>


- ◆ High BG, Low S/N
- ◆ Laser pointing stability
- ◆ laser profile degradation,  $M^2$  worsened  
 Unfocused  $\sigma_{\text{laser}}$  at IP  $\rightarrow$  laser fringe density, low signal
- ◆ beam size jitter (maybe) (if so,  $\sim 20\%$ )
- ◆ relative position jitter between beam and laser fringe




# Comparing typical beam time conditions

	May, 2010	Dec, 2010	Jan-Feb, 2011
Beam size res.	~ 7 %	~ 17 %	
Avg BG energy [GeV]	13 – 20	~ 115 GeV	80 – 130 GeV
S/N	10 - 15 (Max ~ 30)	0.4 – 0.5	Min ~ 0.2 <b>High BG !!</b>
Sig. jitter	8 – 9 % (worst ~ 20%)	20 - 30 %	20 – 60 %
Avg Sig. Energy [GeV]	140 – 250 GeV	50 GeV	50 GeV
Laser spot size [ $\mu\text{m}$ ]	15 – 20	6 deg: ~ 20 8 deg: 25 – 35	35 – 45 Min ~ 25 <b>unfocused Laser !!</b>
ICT [ $10^9$ e-/bunch]	4.5 – 5	3	2 – 5

BG energy during interference scan, Dec, 2010, 6 deg




BG energy during laserwire scan, Feb, 2011, 30 deg



Dec, 2010


May, 2010

avg signal energy




Avg signal energy

avg signal energy




avg BG energy



Avg BG energy

avg BG energy




# Requirements for beam time conditions

Simulation under different BG settings  
(under ideal signal jitters condition)

*Aim for < 10% resolution*

Higher BG tolerable if signal > 50 GeV



parameters	Requirement / goals
BG energy	< 50 GeV <i>at least below signal energy</i>
S/N	> 1
Sig. Energy	> 50 GeV
Sig. jitter	< 10% (20% ok if S/N is high)
Laser spot size	10 – 15 $\mu\text{m}$
Laser pointing stability	< 1 $\mu\text{m}$ @ IP ( $< 50 \mu\text{m}$ @ other PSDs on optical tables)
ICT [ $10^9$ e-/bunch] ICT fluctuation	Around a typical value : 2.5 – 5 < 5%

$$\alpha \rightarrow \alpha + \Delta\alpha$$

$$y \rightarrow y + \Delta y$$

$$\sigma_y^2 \rightarrow \sigma_y^2 + (\Delta y)^2$$

**Phase jitter**

**beam pos jitter**

**beam size**

$$C_{\text{phase}} = \exp\left(-\frac{(\Delta\alpha)^2}{2}\right)$$

$$\Leftrightarrow C_{\Delta y} = \exp\left(-2(k_y \Delta y)^2\right)$$

$$k_y = \frac{2\pi}{\lambda} \sin\left(\frac{\theta}{2}\right)$$

$$\Delta y \Leftrightarrow \frac{\Delta\alpha}{2k_y} = \frac{\lambda \Delta\alpha}{4\pi \sin(\theta/2)}$$

$\Delta\alpha$ [mrad]	$C_{\text{phase}}$	$\Delta y$ [nm] @2°	$\Delta y$ [nm] @8°	$\Delta y$ [nm] @30°	$\Delta y$ [nm] @174°
200	0.98	485	121	33	8.5
300	0.96	728	182	49	13
400	0.92	970	243	65	17
500	0.88	1212	303	82	21

**Correlation between phase jitter and beam pos jitter**


**Typical requirement  $\Delta y < 0.3 \sigma_y^*$**

	2 deg	8 deg	30 deg	174 deg
Beam pos. jitter ( $\Delta y \sim 0.3 \cdot \sigma_y$ )	0.3 x 1 $\mu\text{m}$ = 300 nm	0.3 x 500 nm = 150 nm	0.3 x 100 nm = 30 nm	0.3 x 40 nm = 12 nm
IPBPM res. ( $< 1/3 \cdot \Delta y$ )	< 100 nm	< 50 nm	< 10 nm	< 4 nm


**→ Phase jitter  $\Delta\alpha$  tolerance : 200 – 300 [mrad]**



# Resolving signal jitters



**Signal jitter: 30%**




**Signal jitter < 10%**

after hardware upgrade

Then, we can .....  
**switch modes quicker and easier**

interference scan under  
**stable beam and laser conditions**

- High BG → intermediate collimator
- Beam position → IPBPM + other BPMs
- Beam size jitter → new status display
- Laser position  
 → temperature, vibration stabilization
- Laser profile → deep cleaning, IP clean room




**High BG**



**Investigate new BG source  
→ intermediate collimator**

**Extra post-IP BG source**




**Beam size jitter**



**New  
status display**

**Monitor beam profile, magnet current**

**Beam position jitter**




**IPBPM + upstream BPMs**

Requirement for 30° mode,  $\sigma \sim 100$  nm:

**IPBPM res. < 30 nm**

**Beam position jitter < 50 nm**



New analysis method:

**“atfepics\_full”**

Include data of all ATF2 BPMs

## New status display will also include many other parameters

- IPBSM group may not be present during all beam tuning shifts  
→ need status display that anyone can use / understand
- **Green = OK**
- **Red = call a IPBSM member**

**ex: over 80 parameters in all**

Laser power	
Build-Up	
Laser piezo	
temperature x 14	Mirror Actuator x 14
Nitrogen flow	Rotation stage x 2
	Delay line piezo
Attenuator	
Gamma Shutter	
Laser Shutter	
IP Mover	IP-BPM → beam position (x, y)
BG Monitor IN/OUT	Beam angle (x, y)
Collimator	
Csl(Tl) HV	
	Chamber vacuum
ICT-DUMP	
Csl(Tl) ADC count	Laser Timing
BG Energy	Beam Timing
Signal Energy	Laser - Beam Timing
BG Shower	
Signal Shower	

*2 display panels needed (control room, DAQ room)*

**Ex: current status display (I and II)**  
cannot provide adequate info

EXIT IP-BSM status monitor 1st.(read only)

if ATF-LXS8 reboot, push "READ" button READ

Inserted(ON)

Ejected(OFF)

Ready?

Laser Attenuator

Gamma Shutter

IP Mover

Laser Shutter

BG Monitor

Collimator

Detector HV

Screen Monitor at IP

Laser wire or fringe scan

Show Interlock Circuit

## Laser profile

- ★ Deep cleaning of optical components

*Prevention of a series of problems that may have caused unfocused laser*



→ confirm with laserwire scan

- ★ Clean room around vertical table with air filter



## Laser position stability



## Temperature/ vibration stabilization

- ★ Installed **temperature sensors around entire laser optics** → data logger  
Systematically monitor / analyze long **laser monitor data** (details coming up)
- ★ **Moved laser power unit** (int. cooling water) to inside of laser hut  
**Temp. control unit + laser hut insulation reinforcement**
- ★ **insulation and anti-vibration for mirror box in transport line**



Insulation box


# Laser temperature dependence

Laser + cooling water sensitive to heat effects!!




temperature sensors

*moved laser power source*



Temperature correlation between laser table and (intentionally altered) DAQ room




Switched DAQ room AC on /off to investigate heat exchange between DAQ room and laser hut  
 → Set DAQ room to same temp as laser hut + insulation added

**Now laser temp. very stable!!**

# Example of stabilized temperature #1


*even during a stormy typhoon night !!*

Temperature of laser table and laser clean booth  
{11/9/3 20:00} – {11/9/4 5:00}




laser table

Temperature of laser hut, temp. control unit, and DAQ room  
{11/9/3 20:00} – {11/9/4 5:00}




Laser hut

Temperature of in/outgoing internal cooling water  
{11/9/3 20:00} – {11/9/4 5:00}



Int, ext, cooling water

Temperature of in/outgoing external cooling water  
{11/9/3 20:00} – {11/9/4 5:00}



## Example of stabilized temperature #2

Current typical values and tolerated fluctuation (after 8/30 flash lamp exchange)

From data over 16 hrs

Location	typical values	typical deviation
temp. control unit	25 - 26	0.7
mirror box (upstream)	29.5 - 31.5	2.0
mirror box (downstream)	29.8 - 30.5	1.0
vertical table	28.2	0.1
air pipe in laser hut	25.8	0.3
laser table (lower)	25.8	< 0.1
laser table (upper)	26	< 0.1
top of laser clean booth	23	0.5
DAQ room	23.5	0.2
internal cooling water (in)	29.5	
internal cooling water (out)	32.5	
external cooling water (in)	21	
external cooling water (out)	32.5	




Very small variation at laser table

< 0.1 deg (~ 16 hr)

Without external disturbances, generally very slight fluctuation

May be showing effect of temperature stabilization

# Example of stabilized temperature #3



Temp response pattern for mirror box in transport line

(over ~ 16 hrs)

time for lowest and highest temp generally consistent day to day



# Laser oscillation and interlock

- Laser occasionally failed to simmer on this summer
- **Exchanged mal-functioned flash lamp parts**
- Filter change + power adjustment

Similar problems during last beam run.....

Uncertain of cause (air bubbles?)

Actually may have also been flash lamp + cooling water


*must be cautious to*

- **Check water level, evaporation speed frequently** during long runs
- not only refill, but **exchange all** (no less than once a month)
- water temperature: store box inside laser hut

**Now we can identify and fix problems immediately during beam time!!**

**view/control with PC (RS232C connection)**

- Comprehend error code
- Convenient for detecting time and cause of interlock stop



# Internal Cooling Water Purity

- We measured internal cooling water purity
- Higher value (Unit :  $\Omega$  cm) = higher purity



ATF sample [ $e5 \Omega$ cm]			New cooling water			Cooling water in tank		
7.12	7.19		7.56	7.56		<b>8.78</b>	<b>8.67</b>	
7.01	6.98	6.96	7.55	7.55	7.53	<b>8.65</b>	<b>8.65</b>	<b>8.56</b>
			Similar values in Jan 2011					

- Water already in tank is even purer than new water from box!!!  
 → proves **water filter functions well**

# Laser recovery

after abrupt interlock stop, laser may be unfocused, unstable for a while  
**Investigated recovery time** → prepare for similar cases during beam run

Different components show diverse recovery time

parameter	Recovery time
Build-up, piezo	~ 4 s
Timing (PIN-PD), intensity	~ 12

*Intentionally stopped laser  
for ~ 10 minutes*


location	Recovery time
Laser hut	~ 2 min
Laser table	~ 15-25 min
Cooling water (internal/external)	~ 10-20 min
Laser mirror box	Very slow to respond Almost no effect for short stops

**May have effect  
on operation**


investigated relationship between piezo and build-up timing

- **without external disturbances: Stable build-up, piezo, timing, temp. dependence**



# Example of recovery investigation #1



## Piezo in laser cavity Enlarged 2<sup>nd</sup> stop




## Laser build-up time



# Example of recovery investigation #2

1<sup>st</sup> stop

2<sup>nd</sup> stop




enlarge  
2<sup>nd</sup> stop

## Internal cooling water

out in

10 ~ 20 min until recovery

Similar with external cooling water



# Example of recovery investigation #3

## Laser hut temperature

Response of laser hut temp. demonstrates function of temp. control unit (next to laser hut)


total recovery time ~ 20 min.

DAQ room and the temp. control unit room did not show changes due to the intentional laser disturbances.

Temp. control unit room

Laser hut

DAQ room



2<sup>nd</sup> stop

restart

# Need dedicated beam time for evaluation of beam size resolution

continuous 10 – 20 times of interference scans

**under favorable and consistent conditions !!** (stable beam and laser, S/N, ect...)

repeat for each mode to check for res. consistency

about 45 min each mode ( ~ 3 hrs in all)

## Our responsibility!!

hardware upgrade to prepare for smooth commissioning of 30 , 174 deg modes

## Between all ATF2 groups

Favorable beam conditions

IPBPM !!

well planned shifts

- effective decision making during beam tuning (esp. during mode switching)

- reliable info sharing (ATF wiki, internal reports)

achieve  $\sigma y^* = 37 \text{ nm}$

*important for M. Oroku's D thesis*

# Summary

- ❖ IPBSM “Shintake Monitor” :
- ❖ Only existing device capable of measuring  $\sigma_y^* < 100$  nm
- ➔ Indispensable for beam tuning and realizing ATF2 goals  
(+ realizing future linear colliders!!)
  
- ❖ Recovered from earthquake  
and in preparation for upcoming beam run
- ❖ Past problems include **signal jitters** (laser, beam, BG...)
- ➔ well investigated and planned **hardware upgrades** during summer



## Plans : autumn, 2011 ~

Complete confirmation and upgrade for all modes

Smooth shift to 30 , 174 deg mode  
from 8 deg mode

Close collaboration  
with all beam tuning groups

achieve focusing down to 37 nm



- **BACKUP**

## Example of stabilized temperature #2

Current typical values and tolerated fluctuation (after 8/30 flash lamp exchange)

Location	typical values	typical deviation
temp. control unit	25 - 26	0.7
mirror box (upstream)	29.5 - 31.5	2.0
mirror box (downstream)	29.8 - 30.5	1.0
vertical table	28.2	0.1
air pipe in laser hut	25.8	0.3
laser table (lower)	25.8	< 0.1
laser table (upper)	26	< 0.1
top of laser clean booth	23	0.5
DAQ room	23.5	0.2
internal cooling water (in)	29.5	
internal cooling water (out)	32.5	
external cooling water (in)	21	
external cooling water (out)	32.5	

Much smaller temperature gap between laser mirror boxes upstream and downstream of transport → effect of insulation box

Typical value in Feb, 2011

mirror box (upstream)	18
mirror box (downstream)	21



*Without external disturbances, generally very slight fluctuation*

# Ray PRO interlock system

## Laser head

- Cover

## Cooling water

- flow amount
- Temperature

## Cable connection

## Laser power supply

- Cover

- **Internal cooling water**

- Amount inside tank
- Flow amount

- **External cooling water pressure**

- “ **accessory plug**” :  
external interlock plug

## Controller (on top of power supply)

- Connection to interlock

## Possible causes for laser start up failure

### (1) External cooling water pressure

### (2) Internal cooling water:

- too close down to limit
- Insulation deficit (purity)

### (3) Flash lamp degradation

### (4) HV system faults

ect.....

# Interlock Checklist

- ✓ Switch on **external cooling water**:      **pressure 2.5~4 MPa**
  
- ✓ **Cover of laser head and laser power supply in place**
  
- ✓ **External interlock key switched OFF**
  
- ✓ **Enough internal cooling water** inside tank  
    “Low Water” indicator lamp OFF
  
- ✓ **Lamp energy at START** position (on controller)
- ✓ **Switch ON “ENABLE”**  
    ➔ Pump begin revolving      ➔ “Interlock fault” indicator lamp go OFF

**CDRH should go off and Simmer ON within 10 – 15 sec**

## DAQ modules and controllers **Checklist**

laser attenuator

SHOT204: IP mover , collimator

D250 rotating stage, prizm stage, focal point scanner,

gamma shutter

ip-ccnet

TD4

laser shutter

BGモニタ

RPV171V005L

Discriminator

Thorlabs actuator

TDC

GNV150

Data backup

Actuator for each mirror

Able to move from cpmmand line, from atf-menu, EPICS

atfepics\_full

read out state

AVME500 (phase monitor)

RPV130


- PSD x 12
- Phase monitor x 2
- Laser power
- Build-Up
- Laser piezo
- 
- Attenuator
- Gamma Shutter
- Laser Shutter
- IP Mover
- BG Monitor IN/OUT
- Collimator
- CsI(Tl) HV
- 
- Reducer
- TD4
- Prism Stage
- Focal Point Scanner (upstream)
- Focal Point Scanner (downstream)
- 
- Cross Angle
- ICT-DUMP
- 
- CsI(Tl) ADC count x 12
- BG Energy
- Signal Energy
- 
- Laser Timing
- Beam Timing
- Laser - Beam Timing
- Mirror Actuator x 14
- Rotation stage (upstream)
- Rotation stage (downstream)
- 
- Delay line piezo
- 
- temperature x 14
- Nitrogen flow
- 
- IP-BPM → beam position (x, y)
- Beam angle (x, y)
- 
- Chamber vacuum
- 
- BG Shower
- Signal Shower
- 

86! parameters to monitor


2 display panels needed (control room, DAQ room)

# Monitor function of piezo- electric elements and build-up, intensity, ect....

Ex: anomal  
Proper reset



Proper reset (0V→2V)



correcting heat effects

