



Surface Analysis of the Quench Area Sample of Cavity Z111

W. Singer

More as 60 CVs have been produced at DESY in last 5 Years

Cavities of productions No. 6: XFEL preparation at DESY after **main EP at DESY or at the industry (110 or 140 μm)**

followed by

or

Fine Ep:
Tuning
Final ep (40 μm)
HPR
Installation of FMS
TI-cone rings welding
FM control/ tuning
Tank welding
Removal of FMS
Installation of probes
(HOM /Pick Up)
HQ Antenna (Fixed coupling)
HPR
120 C bake
Acceptance test @ 2K
Ready for module

or


Flash BCP:
Tuning
Installation of FMS
TI-cone rings welding
FM control/ tuning
Tank welding
Removal of FMS
Flash BCP (10 μm)
Installation of probes
HOM /Pick Up
HQ Antenna (Fixed coupling)
HPR
120 C bake
Acceptance test @ 2K
Ready for module

** FMS= field profile measurement system

Cavities of productions No. 6

XFEL Spec. $E_{acc}=23,6$ MV/m

AC-Z cavities



AC BCP Flash

$$E_{acc}=30,2 \pm 4,9$$

Z BCP Flash

$$E_{acc}=24,9 \pm 3,8$$

AC EP


$$E_{acc}=29,3 \pm 9,7$$

Z EP


$$E_{acc}=24,9 \pm 4,4$$

- Max gradient, FE marked, if starts below 20 MV/m
- With He-vessel
- Without HOM pick up



Cavities of productions No. 4 (without He-Vessel)



Statistic of the Eacc in the vertical test as best result




Cavities of productions No. 4,5 and 6 with E_{acc} below 20 MV/m. **5 - cavities Fine-EP treated, 1 cavity BCP - Flash treated (Z111)**



Ta inclusion in the cavity D6

The phenomena for all five Z - cavities seems to be similar. Nevertheless the behavior seems to be different compare to S7-S12 cavities (abrasive particle imbedded), or D6 (Ta inclusion)




Z111 history from TTF database

Cavity Information				CW-Test Results						Power Rise Results											
Cavity	Production No.	Firm	Ingot No.	Removed Material [μm]	Cavity Status	Last HT [$^{\circ}\text{C}$] before Test	Test Date	Test No.	Test Location	Max. Eacc [MV/m]	Q ₀ @ Max. Eacc	Temperature [K]	Limitation	FE Onset		Eacc @ Q ₀ =1E+10	Lowest meas. Q ₀	Q ₀ @ Eacc=23.5 [MV/m]	Lowest meas. Eacc	Eacc @ (100W/9)*cell#	Lowest Loss > (100W/9)*cell#
														@ 4E-4 [mGy/min]	@ 1E-2 [mGy/min]						
Z111	4	Zanon	21	154.8	ep+	800	24.Nov.06	1	v1	16.15	1.8E+10	2	bd			16.15	1.8E+10				
										16.19	1.8E+10	2	bd			16.19	1.8E+10				
Aim: test of cavity first test										Result: not ok: LOw gradient without FE				Remark: No Q disease. Only 16.2 MV/m, Q=1.8E+10, limited by quench, without FE. Processing for 1.5 hour not effective. MM: all cells limited by quench, fields 16.2 (cells 4&6) to 26.6 MV/m (cells 1&9). Low x rays seen in modes 8/9 and 3/9 pi.							
				154.8	ep+	800	07.Dec.06	2	v1	16.03	1.6E+10	2	bd			16.03	1.6E+10				
Aim: test of cavity new test Rotating T mapping mounted										Result: ok				Remark: Cavity is limited by quench at 16.0 MV/m, Q=1.7E+9, without x rays., like in previous test. T mapping done showed that quench is in cell 6 (like one could expect from previous modes measurement) at equator area. New BCP or EP is proposed now for this cavity.							

Totally 155 μm removed


Best CW-Test




Mode measurement Z111; bd without FE

TESLA cavity Z111: #6 cell equator

#6 equator, $t=193 \sim 204$ deg




T-map data in test 2, 16.0 MV/m




group of beads(?) with 1.5mm wide were observed.


Z111, Cell 6, sample 1,
200°.

Quench location








Light microscope. Quench location. Holes along grain boundaries. Cat's eyes.




SEM. Quench location

W. Singer. ILC Cavity Group 9th Meeting. January 27th 2009






SEM. Quench location





SEM. Quench location

W. Singer. ILC Cavity Group 9th Meeting. January 27th 2009





Auger analysis away from flaw areas






Dark and
bright areas



SEM 2008-11-17



Auger analysis of the quench area (no foreign elements)




Auger analysis of the quench area (no foreign elements)



10 μm Nb Z-111#6 Pr1 Detector = InLens EHT = 10.00 kV WD = 10 mm Heraeus

EDX –Analysis
on the black area



Conclusions:






Quench area (Cell 6, Sample 1, 200°)

- Several holes along the grain boundaries are detected on the quench area by SEM
- Holes have sharp edges and looks like corrosion holes
- Several pits observed around the holes
- Auger analysis did not show any indication of the foreign material inclusions on the quench area
- Small black spots close to quench area have been observed. EDX analysis has shown increased content of carbon in these spots
- It is very difficult to imaging that the holes appeared during EB welding. Most probably holes appeared during subsequent treatment

EP: Speculation: how the corrosion holes can appear?

EP: Short circuit (Kurzschluss)??

Electrochemical dissolution of Nb anodes



Recipe:- mixture of hydrofluoric and sulfuric acid (10% HF(40%), 90% H₂SO₄ (96%) KEK)

A **several μm thick** viscous layer of anodic dissolution products is formed: Respect to the bulk of the electrolyte, this layer has higher viscosity and greater electrical resistivity

• What will happened, if in some locations (roots) the viscous layer will not be produced? (zero resistivity, maximal current).

Corrosion is possible

**Thank you very much to the
colleagues of the Fa. W.C. HERAEUS
for the efficient support**

F. Schölz

M. Hoss

D. Watzel