

IP-BSM status and plan: beamtime result in 2010 Nov & Dec




M. Oroku, Y. Yamaguchi, J. Yan, T. Yamanaka, Y. Kamiya, T. Suehara,
S. Komamiya (The University of Tokyo)

T. Okugi, T. Terunuma, T. Tauchi, S. Araki, J. Urakawa
(KEK)

outline



- Result of the beamtime in Nov /Dec of 2010
 - 2-8 degree mode
 - 30 degree mode
 - reasons we could not see the modulation
- Status of the laser
 - Laser focusing problem
 - What happened?
 - some possible reasons
 - Laser timing problems
 - Timing system renewal
 - Detector gate timing
- Plan from 2011 Jan~

2-8 degree mode



- Modulation measured
- Multi knob scans conducted

30 degree mode



- Could **not** see modulation
- Z scan result
-


beam time process

- 12/16
 - 15:30 switch to 30 deg. mode ($M > 0.9$ with 6 deg. mode, corresponding beam size < 350 nm)
 - 17:00 Laser wire scan, reducer scan, z-scan
 - 21:30 beam stop (bad vacuum), laser interlock (lack of cooling water)
 - beam and laser recovered
 - ~tried to find modulation
- 12/17
 - 3:00 switch to 8 deg. mode
 - 10:50 modulation back, $M = 0.68$


Reasons we could not see modulation with 30 degree mode

- Bad S/N ($\sim 1:10$)
 - BG level ~ 100 GeV
 - Signal energy ~ 10 GeV (1/10 of May's run)
 - laser focusing problems (details in Jacqueline's slides)
- Wrong plan
 - Switching from 6 degree mode to 30 degree mode is unrealistic

Confusion of signal fluctuation with modulation (if bad S/N)




Modulation



Fluctuation

- Fluctuation (“fake modulation”) : $\Delta \text{sig} / \text{sig} \sim 0.18$ (for S/N $\sim 1/10$)
- If fake M > expected M, it becomes confusing
- Expected M : 0.17 (300 nm)
- Expected M : 0.42 (200 nm)

Mode switching strategies




higher signal fluctuation
(lower S/N)
requires smaller beam
size for switching mode

| Modulation size [nm] | 6 [deg] | 8 [deg] | 30 [deg] |
|----------------------|---------|---------|----------|
| 300 | 0.92 | 0.88 | 0.17 |
| 250 | 0.95 | 0.91 | 0.27 |
| 200 | 0.96 | 0.94 | 0.42 |

beam time summary


- We could see modulation and conducted multi knob scan with 2-8 degree mode
- We could not see the modulation with 30 degree mode
- Reasons we could not find modulation were bad S/N and wrong strategy




backup

結果 1

set M vs. measured M




結果 2



Plan to do next


- In IP-BSM shift, we need to verify
 - Laser timing is no more jittering
 - Each laser can be focused at IP with 30 , 174 degree
- In continuous run,
 - Try 30 degree mode from 8 degree mode

Signal stability




- Laser wire scan(8 degree mode) with 12 average at each point
- With the same condition, $\Delta\text{sig} / \text{sig}$ at fringe scan will be ~ 0.18

Signal stability with laser wire



12 average at each point

Comparison with Carbon wire (beam time at Dec 10th)



- Multi knob scan(using α_y)
- 2.42 degree mode
- Nominal optics
- BG ~ 40 GeV
- Reasonable result

Focusing problem まとめ

- 下パスのレンズ調整(+2.5 mm)
- 下パスレーザー径増大
- 上パススキャン中、誤った値を入力して一時的に真空悪化
→ビームストップ
- ビーム復旧直後、上パススキャン中、冷却水インターロック
でストップ
- 下パスのレンズ調整(-4.1 mm)
- レーザー復旧後、上パスがでかくなつた
- 上パスは絞れるようになったが、下パスは絞れないままだつた
- 下パスは結局一回も絞れなかつた