



Status Optical Inspection at DESY

- Inspection of Z134, Z136, Z137 and Z142 before chemical treatment „as received“
- T-map of Z131 in all modes and optical inspection of the hotspots afterwards

Z142



Z142




2008/12/16

ILC S0 Cavity Meeting S. Aderhold

As received Zanon cavities

- Optical inspection before treatment shows some defects
- 3 of 4 are back from main EP
- Optical inspection after treatment will follow in 2009

Z131 T-map pi-mode



Z131 cell 1 t=36 deg.




Z131 cell 4 t=228



Z131 cell 9 t=313 deg.



Z131 T-map 3pi/9-mode



Z131 cell 3 t=267 deg.

