

EU Status


- Preparation XFEL
 - Preparation for Call for tender
 - To be ready by April
- Module
 - Re-assembly Module 8
 - Finish by end of March
 - Test M3* finished



M3*


- Warmup to excludes
 - magnetic flux
 - gas condensation
 - Preliminary conclusion
 - Degradation could be a processed field emitter
- Module will be repaired
 - This (as well as the ongoing repair of M8) will block the DESY infrastructure for considerable time
 - Smaller number of tests with EP as final treatment

M8 results on CMTB after the transport





XFEL Preparation: M3**



D. Kostin



XFEL Preparation: M3**

